	IEALTH	2 Y 1		05/20/2015 05/20/2015
• • •	PHYSICAL PPE	0 <sub>Heal</sub>	th Special Hazard	
1. Pro	oduct and	Company	dentification	
Product Code:	101-NEUTRA			
Product Name:	101 Epoxy Bo	ody Coat Part	A (Neutral)	
Trade Name:		ody Coat Part		
Manufacturer Information				
Company Name:	Epoxy Syster	ns, Inc.		
	20774 W Per	nsylvania Ave		
	Dunnellon, Fl	-		
Phone Number:	+1 (352) 489			
Emergency Contact:	PERS (USA)		(800) 633-8253	
Alternate Emergency Contact:	PERS (Intern		+1 (801) 629-0667	
		ds Identif	. ,	
GHS Classification	Placard	Key word	GHS hazard phrase	
Skin Corrosion/Irritation, Category 2	Exclamation point	Warning	Causes skin irritation	
Serious Eye Damage/Eye Irritation, Category 2B	none	Warning	Causes eye irritation	
Skin Sensitization, Category 1B	Exclamation point	Warning	May cause an allergic skin reaction	
Aquatic Toxicity (Acute), Category 2	none		Toxic to aquatic life	
Aquatic Toxicity (Chronic), Category 2	Pollution		Toxic to aquatic life with long lasting effects	
GHS Hazard Phrases				
H315 - Causes skin irritation.				
H320 - Causes eye irritation.				
H317 - May cause an allergic skin	n reaction.			
H401 - Toxic to aquatic life.	1 1 4 7			
H411 - Toxic to aquatic life with	long lasting ef	tects.		
GHS Precaution Phrases	, ,• <b>1</b> ,•••	, <b>.</b>		
P280 - Wear protective gloves/pr		ng/eye protecti	on/face protection.	

P261 - Avoid breathing dust/mist/vapors/spray.

P262 - Do not get in eyes, on skin, or on clothing.

P362+364 - Take off contaminated clothing and wash it before reuse.

P273 - Avoid release to the environment.

### **GHS Response Phrases**

P302+352 - IF ON SKIN: Wash with plenty of soap and water. P332+313 - If skin irritation occurs, get medical advice/attention.

P362 - Take off contaminated clothing.

P305+351+338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P337+313 - If eye irritation persists, get medical advice/attention.

P304+341 - IF INHALED: If breathing is difficult, remove to fresh air and keep at rest in a position comfortable for breathing. P314 - Get medical attention/advice if you feel unwell.

P301+330+331 - IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. P311 - Call a POISON CENTER or doctor/physician.

P391 - Collect spillage.

# SAFETY DATA SHEET

# 101 Epoxy Body Coat Part A (Neutral)

#### **GHS Storage and Disposal Phrases**

P501 - Dispose of contents/container to local, state, and federal authority requirements.

### **Potential Health Effects (Acute and Chronic)**

May cause eye irritation. May cause skin irritation. May cause skin sensitization, an allergic reaction, which becomes evident on reexposure to this material.

#### Inhalation

May cause respiratory irritation.

# Skin Contact

May cause skin irritation. Allergic reactions are possible.

#### **Eye Contact**

Causes eye irritation.

#### Ingestion

May be harmful if swallowed.

#### **Recommended Exposure Limits**

Not established.

#### Medical Conditions Generally Aggravated By Exposure

Skin disorders, Respiratory disorders, Eye disorders, Skin Allergies.

## **OSHA Regulatory Status:**

This material is classified as hazardous under OSHA regulations.

3. Composition/Information on Ingredients		
Hazardous Components (Chemical Name)	CAS #	Concentration
1. Bisphenol-a based epoxy resin	25068-38-6	45 - 55 %
2. Limestone	1317-65-3	30 - 45 %
3. 2,4-Pentanediol, 2-Methyl-	107-41-5	1.0 - 10 %
4. Benzenemethanol	100-51-6	1.0 - 10 %
5. Butyl benzyl phthalate	85-68-7	1.0 - 10 %

# 4. First Aid Measures

### **Emergency and First Aid Procedures**

#### In Case of Inhalation

If inhaled, remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. If experiencing respiratory symptoms: Get medical attention immediately.

#### In Case of Skin Contact

In case of contact, immediately wash skin with soap and copious amounts of water. Remove contaminated clothing and shoes. Get medical attention if irritation develops or persists.

## In Case of Eye Contact

In case of contact with eyes, flush with copious amounts of water for at least 15 minutes. Assure adequate flushing by separating the eyelids with fingers. Call a physician.

### In Case of Ingestion

If swallowed, wash out mouth with water provided person is conscious. Call a physician immediately. Do not induce vomiting. For further assistance, contact your local Poison Control Center.

#### Signs and Symptoms Of Exposure

May cause skin, eye, and respiratory irritation. May cause allergic skin reaction.

	5. Fire Fighting Measures		
Flash Pt:	> 200.00 C Method Used:	Pensky-Marten Closed Cup	
Explosive Limits:	LEL: NE UEL:	NE	

Page: 3 Printed: 05/20/2015 Revision: 05/20/2015

### **Autoignition Pt:**

No data available.

### **Fire Fighting Instructions**

As in any fire, wear a self-contained breathing apparatus in pressure-demand, MSHA/NIOSH (approved or equivalent), and full protective gear.

#### **Flammable Properties and Hazards**

Product is not considered a fire hazard. Closed containers may rupture (due to build up in pressure) when exposed to extreme heat.

#### **Hazardous Combustion Products**

Hazardous decomposition products formed under fire conditions. Carbon dioxide, Carbon monoxide.

#### Suitable Extinguishing Media

Dry chemical, CO2, water spray or regular foam.

## **Unsuitable Extinguishing Media**

Do not use a direct water stream, which may spread fire.

# 6. Accidental Release Measures

#### Steps To Be Taken In Case Material Is Released Or Spilled

PROCEDURE TO BE FOLLOWED IN CASE OF LEAK OR SPILL.

Absorb with sand or vermiculite and place in closed containers for disposal. Ventilate the area.

#### **Protective Precautions, Protective Equipment and Emergency Procedures**

Wear respirator, chemical safety goggles, rubber boots, and heavy rubber gloves. Where splashing is possible, full chemically resistant protective clothing, and boots are required.

#### **Environmental Precautions**

Prevent entry into waterways, sewers, basements or confined areas.

# 7. Handling and Storage

### Hazard Label Information:

Avoid contact with skin and eyes. Do not get on skin and clothing. Avoid inhalation of vapor or mist. Store in a closed container.

#### **Precautions To Be Taken in Handling**

Provide adequate ventilation. Do not breathe vapor. Do not get in eyes, on skin or on clothing.

#### **Precautions To Be Taken in Storing**

Keep container tightly closed in a dry and well-ventilated place.

## **Other Precautions**

Wash thoroughly after handling.

8. E	Exposure (	Controls	/Personal	Protection
------	------------	----------	-----------	------------

Hazardous Components (Chemical Name)	CAS #	OSHA PEL	ACGIH TWA	Other Limits
1. Bisphenol-a based epoxy resin	25068-38-6	No data.	No data.	No data.
2. Limestone	1317-65-3	PEL: 15 (dust); 5 (resp.) mg/m3	No data.	No data.
3. 2,4-Pentanediol, 2-Methyl-	107-41-5	8	TLV: 25 ppm CEIL: 121 mg/m3	No data.
4. Benzenemethanol	100-51-6	No data.	No data.	No data.
5. Butyl benzyl phthalate	85-68-7	No data.	No data.	No data.

#### **Protective Equipment Summary - Hazard Label Information:**

Neoprene gloves Safety glasses, or goggles. I

Impervious clothing. Chemical resistant boots

### Respiratory Equipment (Specify Type)

Normally when good engineering controls are used, no respiratory protection is needed. However, if cured product is abraded by sanding or grinding use a NIOSH approved air-purifying respirator. Where risk assessment shows air-purifying respirators are appropriate use a dust mask type N95 (US) or type P1 (EN 143) respirator. A NIOSH/MSHA approved air purifying respirator with an organic vapor cartridge or canister may be permissible under certain circumstances where airborne concentrations are expected to exceed exposure limits. Protection

provided by air purifying respirators is limited. Use a positive pressure air supplied respirator if there is any potential for an uncontrolled release, exposure levels are not known, or any other circumstances where air purifying respirators may not provide adequate protection.

#### **Eye Protection**

Safety glasses, or goggles.

### **Protective Gloves**

Nitrile rubber and Neoprene are recommended.

#### **Other Protective Clothing**

Where splashing is possible, full chemically resistant protective clothing, safety glasses or face shield and boots are required.

## **Engineering Controls (Ventilation etc.)**

Good general ventilation should be sufficient to control airborne levels. Safety shower and eye bath.

## Work/Hygienic/Maintenance Practices

Wash contaminated clothing before reuse. Discard contaminated shoes. Wash thoroughly after handling.

### **Environmental Exposure Controls**

Avoid runoff into storm sewers and ditches which lead to waterways. May be hazardous to the environment if released in large quantities.

9. Physical and Chemical Properties			
Physical States:	[]Gas [X]Liquid []Solid		
Melting Point:	NE		
Boiling Point:	NE		
Decomposition Temperature:	NE		
Autoignition Pt:	No data.		
Flash Pt:	> 200.00 C Method Used: Pensky-Marten Closed Cup		
Explosive Limits:	LEL: NE UEL: NE		
Specific Gravity (Water = 1):	~ 1.378		
Density:	~ 11.49 LB/GL		
Vapor Pressure (vs. Air or mm Hg):	NE		
Vapor Density (vs. Air = 1):	NE		
Evaporation Rate:	NE		
Solubility in Water:	~		
Solubility Notes			
Practically insoluble.			
Percent Volatile:	N.A.		
VOC / Volume:	NP		
HAP / Volume:	NP		
Saturated Vapor Concentration:	NE		
Appearance and Odor			
Epoxy odor.			
Appearance: Liquid. Milky.			
	10. Stability and Reactivity		

# Stability:

Unstable [ ] Stable [ X ]

## Reactivity

Avoid: acids, alkalis, oxidizing agents.

# SAFETY DATA SHEET

101 Epoxy Body Coat Part A (Neutral)

Page: 5 Printed: 05/20/2015 Revision: 05/20/2015

#### **Conditions To Avoid - Instability**

Extreme temperatures.

#### Incompatibility - Materials To Avoid

Avoid strong acids, bases, and oxidizing agents.

#### Hazardous Decomposition Or Byproducts

Thermal decomposition may produce smoke, carbon monoxide, carbon dioxide.

Possibility of Hazardous Will occur [ ] Will not occur [ X ]

#### **Polymerization:**

#### **Conditions To Avoid - Hazardous Reactions**

Will not undergo hazardous polymerization in normal storage conditions.

# **11. Toxicological Information**

#### **Toxicological Information**

May cause sensitization by skin contact.

#### **Chronic Toxicological Effects**

Skin sensitization.

#### **Irritation or Corrosion**

Skin Irritation. Irritating to eyes.

#### Symptoms related to Toxicological Characteristics

May cause redness, rash on skin.

	На	zardous Components (Chemical Name)	CAS #	NTP	IARC	ACGIH	OSHA
	1.	Bisphenol-a based epoxy resin	25068-38-6	n.a.	n.a.	n.a.	n.a.
	2.	Limestone	1317-65-3	n.a.	n.a.	n.a.	n.a.
	3.	2,4-Pentanediol, 2-Methyl-	107-41-5	No	No	No	No
	4.	Benzenemethanol	100-51-6	n.a.	n.a.	n.a.	n.a.
	5.	Butyl benzyl phthalate	85-68-7	n.a.	3	n.a.	n.a.
r							

# **12. Ecological Information**

#### **General Ecological Information**

Avoid release to the environment. May be hazardous to the environment if released in large quantities.

## Results of PBT and vPvB assessment

## No data available.

Persistence and Degradability

Not readily biodegradable.

# **Bioaccumulative Potential**

No data available.

#### **Mobility in Soil**

not reported, unknown.

# **13. Disposal Considerations**

#### Waste Disposal Method

Incinerate or dispose of unused material, residues and containers in a licensed facility in accordance with all applicable local, state and federal regulations. Do not discharge substance/product into sewage system.

# **14. Transport Information**

# LAND TRANSPORT (US DOT)

DOT Proper Shipping Name

(Non-Bulk) Not Regulated.

(Bulk)

Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE POLLUTANT.

	NOTE: Marine Pollutants - DOT requirements specific to Marine Pollutants do not apply to non-bulk packagings transported by motor vehicles, rail cars or aircraft.
DOT Hazard Class:	9
DOT Hazard Label:	CLASS 9
UN/NA Number:	UN3082
Packing Group:	111
Precautionary Label	Avoid skin and eye contact. May cause eye and skin irritation. May cause skin sensitization. Wear protective equipment and clothing. Always read MSDS/SDS before use.
AIR TRANSPORT (ICAO/IATA)	
ICAO/IATA Shipping Name	(Non-Bulk) Not Regulated.
	(Bulk) Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE POLLUTANT.
	NOTE: Marine Pollutants - DOT requirements specific to Marine Pollutants do not apply to non-bulk packagings transported by motor vehicles, rail cars or aircraft.
UN Number:	3082
Hazard Class:	9 - CLASS 9
Packing Group:	III
MARINE TRANSPORT (IMDG/IMO)	
IMDG/IMO Shipping Name	Environmentally hazardous substance, liquid, n.o.s. (Epoxy Resin) MARINE POLLUTANT.
	Note: The presence of a shipping description for a particular mode of transport (ocean, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. Shipment compliance is the responsibility of the person offering the product for transport.
UN Number:	3082
Hazard Class:	9 - CLASS 9
Packing Group:	III
IMDG MFAG Number:	FA,SF
Marine Pollutant:	Yes

# 15. Regulatory Information

### **Regulatory Information**

SARA 302 Extremely Hazardous Substances: None.

SARA Section 311/312: Acute Health Hazard.

SARA 313 Toxic Chemicals: None.

CERCLA Reportable Quantity: None.

# **16. Other Information**

CA=CIRCA NA=NOT AVAILABLE NE=NOT ESTABLISHED NR=NOT REGULATED NP= NOT APPLICABLE PR=PROPRIETARY TS=TRADE SECRET ?=UNKNOWN.

## **Company Policy or Disclaimer**

The information contained in this MSDS is taken from sources believed to be accurate as of the date hereof; however Epoxy Systems, Inc. makes no expressed or implied warranty in respect to the accuracy of the information or the suitability of the recommendations, and assumes no liabilities to any user thereof.

#### **Revision Date:**

05/20/2015